STATE OF WASHINGTON

DEPARTMENT OF FISH & WILDLIFE LANDS AND RESTORATION SERVICES PROGRAM

Salmonid Screening, Habitat Enhancement & Restoration Division (SSHEAR)

OFF-CHANNEL SITE INVENTORY DATA

General Information:

Region: North Coast Observer(s): Nettnin

River System: Sol Duc Date: 2/12/97

Site Identifier: S-304L-07 WRIA: 20.0304 B

River Mile Location: 3.8 RB/LB: LB

Local Name: Unnamed Trib. to: W.F. Gunderson Creek

Legal Description: NW¼ Sec 17 T29N R13W **County:** Clallam

Habitat Type: Lower valley wall trib

Landowner: () Federal (X) State () County () Other Government (X) Private

Department of Natural ResourcesRayonier Timber Operations Company

Directions to site:

Head north from Forks on HWY 101 to M.P. 198.1. Turn left (west) onto the T-1000, then an immediate left onto the T-1010. Proceed to road junction and gate (0.3 mi.) a key can be obtained from Department of Natural Resources office or from the Rayonier Timber Operations Company in Forks. Continue up the road for about 1.5 mi., to the north end of Gunderson Mountain. The first stream crossing is S-304L-07.

Site Overview:

This second order stream drains about 40 - 80 acres. It sources on the valley wall and then meanders over the toe of the valley wall and the valley floor to join The W.F. Gunderson Creek. It is presently a timbered watershed that produces gravel for the Gunderson system. It is intermittent at the lower reach during dry spells, even in the winter.

Habitat Information:

Water source: surface runoff

Intermittent/year-around: Intermittent

Estimated flows (cfs): Lower end: 0.25 - 0.5 Upper end: 0.2 - 0.5

Water temperatures: Lower end: 5.5°C Upper end: 5.5°C

Adjacent stream temperature (W.F. Gunderson Creek 20.0304): 5.5°C

Other water observations: clear water

Site area measurements: () Indirect () Direct (X) Combination

Widths: Channel- 1.0 - 2.0 m Ponds- NA Wetlands- NA Depths: Channel- 5 - 10 cm Ponds- NA Wetlands- NA

Total length surveyed: 350 m

Total existing habitat area (est.): 370 m²

Spawning area: None Impounded area: None Other rearing area: 370 m²

Spawning Habitat conditions: () None (X) Poor () Fair () Good () Excellent

Describe spawning habitat:

- There is good gravel for spawning, but the lower end goes subsurface during dry spells.

Rearing habitat conditions: () None (X) Poor () Fair () Good () Excellent

Describe pond and other rearing habitat:

- Lower reach goes subsurface during dry spells.
- Middle reach is moderate gradient and better suited for trout, but may get intermittent flows also.

Describe unaccessible habitat: None

Describe wetland: () Bog () Marsh () Scrub-shrub Wetland () Forested Wetland

- None

Flooding potential: (X) Low () Medium () High

- Does receive high flows during storm events.

Fish Information:

Site entry condition to W. F. Gunderson: () Poor (X) Fair () Good

- The culvert outlet spills into the W.F. Gunderson. There is small plunge pool with a 15 cm drop out of the culvert.

Coho access and use:

Juvenile- (X) Unknown () None () Poor (X) Fair () Good Adult- (X) Unknown () None () Poor () Fair () Good

Other species access and use: () Chum () Sockeye () Chinook (X) Trout () Res. Trout It is unknown if trout use this system, but there is open access.

Habitat Improvements:

Enhancement opportunities:

- Maintain the integrity of the stream.

Additional Comments:

- The culvert appears to be in good shape and is not a problem at this time

Attachments Available:

Contact respective SSHEAR habitat biologist for the following checked items:

(X) Aerials (X) Sketch () Juvenile trapping (X) Culvert Report

() Other references () Spawning surveys () Fishway Report (X) Maps





